


2801651

09/847264

20/1

FIG. 23







FIG 24

102780-1324860



FOE F50-19271860





FIG 1A

FOOT-50-1924-850






Fig 3




Fig 4







Fig 5



FOOTING 1924-1930

Fig 9




Fig 10




Fig 11




Fig 12





Fig 13

09847294.004304

Fig 14




Fig 15




Fig 16





FIG. 10



17A

09847264-084 394
FOR FIG. 17B

FIG 17 B




FIG. 17C







FIG. 17C

[illegible]

[illegible]

0847264-0847374

19A







FIG 19B

